$S_{\mathbb{R}}$

Sony Service Company National Technical Services A Division of Sony Electronics Inc. Park Ridge, New Jersey 07656

CONFIDENTIAL

CSV-1

Service Bulletin TV Products

Model: KP-41T35, KP-41T65, KP-46C36, KP-46C65,

KP-48S35, KP-48S65, KP-48V45, KP-48V75

KP-53S35, KP-53S65, KP-53V45, KP-53V75, KP-61S35, KP-61S65, KP-61V45, KP-61V75

Subject: Countermeasure for Video Amp IC failure and

Date: November 16, 1998

380

No.

CRT phosphor damage.

Symptom:

(1311) Video Amp failure with possible CRT damage, due to CRT arcing

Solution: If the above symptom should appear please add the following:

- 1. Mount a diode on the "solder" side of all three CRT boards CR, CG, and CB boards. The diode should be mounted across IC701/pin6 and 8 to the three See fig 1.
- 2. Redress the HV leads and use a Tie lock to attach the FBT lead to the Anode lead for the Red CRT. See fig 2
- 3. Place RTV over the diode to secure it to the board.

| Description | Part Number |
|---------------|--------------|
| Diode 1SS83TD | 8-719-975-24 |
| Tie lock | 4-049-280-01 |

Cont.




Fig 1

