

Model: KP-43T70, KP-43T75, KP-46C70, KP-48S75, KP-48V85, KP-53N74, KP-53N77, KP-53S75, KP-53V85, KP-61S75, KP-61V85 **No. 491**

Subject: Part Number Corrections: Front Panel Control Door **Date:** July 27, 2000

Symptom:
(****) The part numbers shown in the service manuals are incorrect for some of the front panel control doors.

Solution: Please make the following corrections to your service manuals.

REF	MODEL	CONTROL DOOR PART NUMBER	
		INCORRECT	CORRECT
19	KP-43T70	4-069-660-11	4-073-437-11
-	KP-43T75	-	4-073-437-11
75	KP-46C70	4-069-671-01	4-069-671-21
75	KP-48S75	4-069-659-01	4-069-659-11
3	KP-48V85	4-069-671-11	4-069-671-21
125	KP-53N74/53N77	4-069-671-01	4-069-671-21
125	KP-53S75/61S75	4-069-659-01	4-069-659-11
53	KP-53V85/61V85	4-069-671-11	4-069-671-21

Control Door (KP-43T70 shown, other models are similar)

